



CAM2301

FIRMWARE RELEASE NOTE

#	VERSION	DATE	DESCRIPTION
01	00.06.1162	OCT 16 2023	Original version
02	05.06.1433	APR 12 2024	<u>Optimization</u> Unsynchronized Events between SD Card and Cloud <u>New Feature</u> 1. Playback 2. Successful IoT Connection – Log Notification
03	07.06.1589	FEB 24 2025	<u>Fix</u> Dynacam APP Connection Issue
04	07.06.1607	AUG 22 2025	<u>Fix</u> 1. Snapshot File Name and OSD Time Synchronization 2. LAN/Wi-Fi Clients Unable to Ping the AP or Router 3. VMS Playback Issue
05	07.06.1614	DEC 21 2025	<u>Optimization</u> 1. Log File Size 2. Web UI: SSID Information



Civil IoT



Smart Transportation



Smart Home



Smart Manufacturing



Smart Building



Smart Area

Manufacturing Experiences.

Since 1989.